



| | ACO | POS | BIT | QUANT | COMPRIMENTO | TOTAL |
|------|-----|-----|-----|-------|-------------|-------|
| | | | mm | | UNIT | cm |
| B1 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 4 | 259 | 1554 |
| B2 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 4 | 257 | 1028 |
| | 50A | 3 | 10 | 4 | 259 | 1036 |
| B7 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 4 | 257 | 1028 |
| | 50A | 3 | 10 | 4 | 259 | 1036 |
| B15 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B23 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B40 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B41 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B49 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B50 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B60 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B61 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B63 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B92 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B93 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B100 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B105 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B106 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B116 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 6 | 259 | 1554 |
| B123 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 6 | 257 | 1542 |
| | 50A | 3 | 10 | 4 | 259 | 1036 |
| B124 | 60A | 1 | 5 | 4 | 315 | 1260 |
| | 50A | 2 | 10 | 4 | 257 | 1028 |
| | 50A | 3 | 10 | 4 | 259 | 1036 |

| RESUMO DE AÇO | | | | |
|---------------|-----|-------|------|-----|
| AÇO | BIT | COMPR | PESO | |
| 60A | 5 | 252 | n | kgf |
| 50A | 10 | 578 | n | kgf |
| Peso Total | | 60A = | 38 | kgf |
| Peso Total | | 50A = | 357 | kgf |